

APPROVED BY W. A. 122

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

1st Survey
1945

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	REPORT OF WATER ANALYSIS
NOTICE OF INTENTION TO CHANGE PLANS	REPORT OF RESULTS OF TESTING OR ANALYSIS
NOTICE OF INTENTION TO TEST EXISTING WELL	REPORT OF ALTERATION OF WELL
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	REPORT OF RESULTS OF TESTING OR ANALYSIS
NOTICE OF INTENTION TO SHOOT OR ABANDON	REPORT OF RESULTS OF TESTING OR ANALYSIS
NOTICE OF INTENTION TO PULL OR ABANDON CABLE	REPORT OF RESULTS OF TESTING OR ANALYSIS
NOTICE OF INTENTION TO ABANDON WELL	REPORT OF RESULTS OF TESTING OR ANALYSIS

Give name of person or company who has been authorized to make the work described in this report.

Well No. 22 is located 1/2 mile from the SE corner of Sec. 22
NE 1/4, NE 1/4, Sec. 22
(T. 2N., R. 2E., S. 22)
NE 1/4, NE 1/4, Sec. 22
(T. 2N., R. 2E., S. 22)

The elevation of the derrick floor above sea level is 1000 ft.

State names of and reported depths to the top of the following formations or strata, and the nature of the formations or strata.

It is stated by the operator that the well is a water well and that the water is fresh and good for drinking. The well is 1000 ft. deep and the water is 1000 ft. from the surface.

I understand that this plan of work must be approved by the Bureau before operations are begun.

Company Standard Oil Company

Address P. O. Box 1000

Chicago, Ill.

W. A. 122
Director