DEPARTMENT OF THE INTERIORHobbs, NM Council BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposeds to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposeds) SUBMIT IN TRIPLICATE	Form Approved By Carlabad, NM BLM, 1/24/04 5. Lease Designation and Serial No. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Well Name and No.
DEPARTMENT OF THE INTERIORHobbs, NM41 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals) SUBMIT IN TRIPLICATE	<ol> <li>If Indian, Alloties or Tribe Name</li> <li>If Unit or CA, Agreement Designation</li> <li>Well Name and No.</li> </ol>
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals) SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation 8. Well Name and No.
SUBMIT IN TRIPLICATE	8. Well Name and No.
	Johns "B" No. 3
Fina Oil & Chemical Company	30 - 025 - 00698 10. Field and Pool, or Exploratory Area
P O Box 10887, Midland, TX 79702-0887	Maljamar (Grayburg- 11. County or Parish, State
660' FSL & 1980' FEL, Sec 26, E-17-S, R-32-E	Lea
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT TYPE OF SUBMISSION TYPE OF ACTION	T OR OTHER DATA
	Change of Plans New Construction
Subsequent Report     Plugging Back       Casing Repair	Non-Routine fracturing Water Shut-Off
Final Abandonment Notice	Conversion to Injection Dispose Water
(Note: Report results of multiple completion on Weil Completion or Record	
give adjustance locations and measured and two vertical depths for all markers and zones performent to this work) <sup>4</sup> On 4/7/86, a 5 1/2" CIBP was set at 4000' GL. The wellb with 100 barrels of packer fluid. The casing was press psi and held okay. On 5/13/93 the casing was retested integrity. Pressure of 500 psi was applied for 30 minut leakoff occurred during the test under the supervision sentative. On 2/18/97 the casing was retested for mech Pressure of 500 psi was applied for 30 minutes. No obs leakoff occurred.	sure tested to 500 for mechanical ces. A 10 psi of a BLM repre- nanical integrity.
Fina is currently evaluabing the viability of re-complet the Queen formation (-3500') or utilizing the well for for the Johns B #4. We expect to complete the evaluati appropriate action within 9 to 12 months. Therefore, we the well be allowed to remain temporarily abandoned for	salt water disposal on and take we request that
Note: a copy of the CIT chart taken in 1997 is attached The original should be in your files as submitted in Ap 14. thereby copying they have going that an approximate	for your reference. oril, 1997.

Signed <u>Clash</u> <u>H</u> <u>H</u> <u>Ed</u> <u>P</u> <u>X</u> <u>C</u> <u>C</u> <u>C</u> <u>C</u> (This space for Federal or State office uncon Approved by	<u> </u>	Engineering Advisor ROLEUM ENGINEER	MAR 2 9 1999
Conditions of approval, if any:		12-MONTH PERIO	
Tite 18 USC Section 1001 mekes if a crime i		1 1 8 2000	rauchient statements
or representations as to any matter within its j		•	
IW	*See Instruc	tions on Reverse Side	
26		V	c

