


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Maljamar, New Mexico November 2, 1950

FRANKLIN "A" LEASE

Well No. 3 is located 660 ft. from S line and 1900 ft. from W line of sec. 33

NW 1/4, Sec 33

(1/4 Sec. and Sec. No.)

17S

(Twp.)

3E

(Range)

N.M.P.M.

(Meridian)

Franklin

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3096.5 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On October 28, 1950 ran 7" OD - 30' - 8' 3rd and - New Casing (1616' of 355 and 1483' of 140) and set down at 1400'. Ran 1/2 sacks of Aquagel ahead of cement and cemented with 100 sacks of cement cement. Pumped plug to 1400' and banded float collar. Cementing done by Halliburton Oil Well Cementing Company.

Let well stand for 72 hours for cement to set. After drilling plug tested well for 2 hours and found water to be shut off. Started drilling ahead on October 31, 1950.

Confirming telephone conversation with Mr. John A. Frost, U.S.G.S., Artesia, N. M. on October 27, 1950.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kennecott Oil CompanyAddress P. O. Box 207Maljamar, New Mexico

By

Title

Ramsey
District Superintendent

