(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office ___*Las Cruces*___

Lease No. ___*058407-B*___

Unit ___*Johns*___

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING *Frac*	*X*
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

___*1-24*___, 19 _*57*_

Well No. __*2*__ is located __*660*_ft. from $\boxed{S}$ line and _*990*_ ft. from $\boxed{W}$ line of sec. _*35*_

___*178*___	_*32E*_	___*NMPM*___	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
___*Pearsall*___	___*Lea*___	___*New Mexico*___	
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is __*3960*_ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was making 3 1/2 bbls. oil and 4 bbls water per day. We fraced well with 10,000 gals. and 10,000 lbs. sand. We have now recovered our frac oil and well is now making 13 bbls. of oil and 65 bbls of water per day. No increase in gas - An increase in allowable has been requested.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ___*Water Drilling Company*___

Address ___*Box 716, Monahans, Texas*___

By ___*R. C. Brandon*___

Title ___*Secy-Treas.*___