

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Murphy H. Baxter, 507 Midland National Bank Building, Midland, Texas
(Address)

LEASE State "18-B" WELL NO. 3 UNIT I S 18 T-17-S R-33-E
DATE WORK PERFORMED 7-19-58 POOL Maljamar

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran and cemented 150 Jts. (4595.99') of 5 1/2" 14# J-55, STAC 8RT new smls. casing @ 4506.29' w/150 sx 4% gal Reg. cement & 120 sx of Dowell Cement. W.O.C. 48 hrs. Landed casing, nipples up Xmas tree & tested casing w/1500# for 30 minutes. Pressure held OK.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____
Oil Production, bbls. per day _____
Gas Production, Mcf per day _____
Water Production, bbls. per day _____
Gas-Oil Ratio, cu. ft. per bbl. _____
Gas Well Potential, Mcf per day _____
Witnessed by _____

OIL CONSERVATION COMMISSION

Name [Signature]
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name [Signature]
Position Owner
Company Murphy H. Baxter