

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Murphy H. Baxter		Address 507 Midland National Bank Bldg. Midland, Texas					
Lease State "18-13"	Well No. 1	Unit K	Section 18	Township 17-S	Range 33-E		
Date Work Performed March 7, 1959	Pool Maljanar			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spudded @ 7:00 P.M. 3-6-59 w/12 $\frac{1}{2}$ " bit. Drilled 12 $\frac{1}{2}$ " hole to 319'. Ran and cemented 10 Joints (305.78') of 8 5/8" 24# 8RT J-55 ST&C new Spang casing @ 317.78' with 150 sax HONCO 4% Gel cement. Cement circulated. WOC 24 hours. Nipped up blow out preventors and tested casing with 1000# for 30 minutes. Casing tested OK.

Witnessed by M. D. Lewis	Position Production Supt.	Company Murphy H. Baxter
------------------------------------	-------------------------------------	------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

I hereby certify that the information given above is true and complete to the best of my knowledge.

OIL CONSERVATION COMMISSION

Approved by

Title

Date

Name

Position

Company

Petroleum Engineer**Murphy H. Baxter**