ENERGY AND MINERALS DEPARTMENT	
C CONSERVATION DIVISION	
DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE, NEW MEXICO 87501	Revised 10-1-75
U.1.G.S.	Sa. Indicate Type of Lease
LAND OFFICE	State X Fee
OPEHAYGA	5. State Oil & Gas Lease No.
	B-2148
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FOR FOR PROPOSALS TO UPILL OR TO DECEMENT OF PLANE CHOIL OR PLACE TO A DIFFERENT RESERVOIR.	
	7. Unit Agreement Name
well & well other. Allow well of	
Name of Operator	8. Farm or Lease liame
Pennzoil Company	Western State
P.O. Drawer 1828, Midland, TX 79702 $\int W^{-1} \psi^{-1}$	9. Well No.
Location of Well	4 10. Field and Pool, or Wildcut
UNIT LETTER H 1980 FEET FROM THE NOTTH LINE AND 660 FEET FROM	Maliaman Chu Ch
UNIT LETTER,,, FEET FROM THELINE AND FEET FROM	
THE East LINE, SECTION 20 TOWNSHIP 17-S RANGE 33-E	AHHHHHHHHAA
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
4176 GR	Lea AllIIIIi'
Check Appropriate Box To Indicate Nature of Notice, Report or Other Notice of Intention To:	her Data. I REPORT OF:
PERFORM RELICOIAL WORK PLUG AND ABANDON REMEDIAL WORK	
ICMPORANILY ABANDON	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	FLOG AND ABARDONMENT LA
OT HER	
OTHER	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated data of stanian and stanian
work) see RULE 1103.	commerce case of starting any propose?
9-16-86: MIRU Pulling Unit. Lay down rods and pump. TOH with 100 jt	s of 2-7/8" tbg.
9-17-86: Finish TOH w/tbg and anchor. TIH w/AD-1 tension packer and	
20,000 lbs. tension. Pumped down the annulus to test the csg and the	
Moved packer to 220' and tested csg, the csg did not test. POH w/th $w/6-1/4''$ bit to 4000' and TOH w/same. TIH w/7'' Baker cmt retainer t	og and packer. TIH
•	
9-18-86: Finish TIH w/cement retainer and set at 3965' KB. Establish	
of 4-1/2 BPM at 1250 psi. Squeeze below cement retainer w/100 sx C1 to 2100 psi while pumping slurry. Pulled out of retainer and spotte	
on top of retainer. TOH w/tbg and stinger. Pressure test the 7" cs	
minutes. Held ok.	8 For
9-19-86: TIH open ended to 3900'. Load hole w/10# salt gel brine muc	TOH lawing down the
Perforate 4 1/2" holes at 275'.	. Ion laying down LDg.
9-20-86: Weld a 2" nipple and valve in 12 3/4" csg. TIH w/tbg and AI	L topoion notice
set at 210'. Break circulation, obtain good circulation. Unseat pa	
Nipple down BOP and cut off wellhead. Weld a 7" x 2" swage on the 7	
sx Class "H" neat cmt down 7". WOC - 4 hrs. Pump 2 bbls & broke ci	
	(OVER)
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
$\gamma \gamma \mu$	1- X-Conte
ICHER Mark Stumuly TITLE Engineer	DATE 10-1-86
OIL & GAS INSPECTOR	A A A A
PPROVED AL VERIAL SMARS HELE	DATE ALTO LUUR
ONDITIONS OF APPROVAL, IF ANYI	
	5
	2

9-21-86: Pressure tested 7" csg to 1200 psi. Held ok. Tagged cmt at 51'. The state field rep. (Ray Smith) said job ok. Put 10 sx cmt down annulus between 7" and 12-3/4" and filled cellar with cement. Installed dry hole maker, cleaned up location. Well P&A on 9-20-86.

.

