Budget Bureau 42-R358.2. Approval expires 12-31-52.

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Griess
Lease No
Unit F

Elliett

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHU NOTICE OF INTENTION TO RE-DRILL OR REI NOTICE OF INTENTION TO SHOOT OR ACIDIZ NOTICE OF INTENTION TO PULL OR ALTER	PAIR WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
	E BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
	1930 ft. from $\begin{bmatrix} N \\ K \end{bmatrix}$ line and 1930 ft. from $\begin{bmatrix} W \\ W \end{bmatrix}$ line of se	, 19_52

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Commented 4516 fort of 9 5/Swinch ensing at 4531 feet with 2000 sacks of Halliburton 101 Linghern Jol and 100 seeks of Portland cent event. Circulated out approximately 155 sasks comment. Casing jumped out of collar 97' from surface. Second stage - After tying easing back together, recommented pipe with 75 mocks Foriland meet desent. Circulated 25 packs excess operat to surface. Sected at 9:07 a. m. to 9:38 a. m. S-2-52. Applied 2008 pri for 30 minuter. Se drep in propure. Frilled out essent 40 foot to 124 feet. Tested perforation and cement job below shee with 800% for 30 minutes. Sent down to float collar and tested remainfor of saving 30 sinutes with 800 #. Tested C L. Made 3 foot hals and tested sevent job autaide of making with 900s for 30 simutes. Tested 0 K. Brilling Continues.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Perining Company

Address Best 2347

Nobbe, Nev Hexico

Title listr et aperintendent