

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-604	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name -
2. Name of Operator Morris R. Antweil		8. Farm or Lease Name N.M. "AH" State
3. Address of Operator P. O. Box 2010, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM West 36 TOWNSHIP 15S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Townsend Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4046' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows:

Spotted 25 sx cement plug across perfs 9640' - 9658' ,
Cut & pulled 3100' 5 1/2" casing,
Spotted 25 sx cement plug across 5 1/2" casing stub @ 3100' ,
Cut & pulled 800' 9 5/8" casing,
Spotted 25 sx cement plug across 9 5/8" casing stub @ 800' ,
Spotted 25 sx cement plug across 13 3/8" casing shoe @ 423' ,
Spotted 10 sx surface plug w/marker.
Hole was loaded with mud-laden fluid,
Plugged & Abandoned 25 February 1969.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R M Williams</u>	TITLE <u>Agent</u>	DATE <u>2/26/69</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		