

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Union Oil Company of California		8. Farm or Lease Name Hume Queen Unit	
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N. M.		9. Well No. 1	
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>7</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Hume Queen	
11. Elevation (Show whether DF, RT, GR, etc.) 4150' SCF		12. County Lea	

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Spotted a 25 sx cement plug from 3924'-3944'.
2. Spotted a 25 sx cement plug at 5 1/2" casing stub at 1400'.
3. Spotted a 25 sx cement plug at 8-5/8" casing shoe at 352'.
4. Spotted a 10 sx cement plug at surface with marker.
5. Hole was loaded with mud-laden fluids.
6. No casing was recovered.
7. Well was plugged and abandoned on 6/28/71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 7/16/71

APPROVED Nathan E. Olegg TITLE OIL & GAS INSPECTOR DATE JAN 25 1972  
CONDITIONS OF APPROVAL, IF ANY: