

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Oil Company Of California	8. Farm or Lease Name Hume Queen Unit
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N.M. 88240	9. Well No. 7
4. Location of Well UNIT LETTER H , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 16-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Hume Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4139' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 30 sx cement plug from 3938'-3960'.
2. Spotted a 25 sx cement plug at 5 1/2" casing stub at 1105'.
3. Spotted a 25 sx cement plug at 8-5/8" casing shoe at 348'.
4. Spotted a 10 sx cement plug at surface with marker.
5. Hole was loaded with mud laden fluids.
6. Well was plugged & abandoned on 11-11-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>H. Schmidt</i>	TITLE Agent	DATE 11/27/70
APPROVED BY <i>John W. Remy</i>	TITLE Geologist	DATE 11/27/70
CONDITIONS OF APPROVAL, IF ANY:		