NEW MEXICO OIL MISCELLAN (Submit to appropriate Distr	IEOUS REPC	ORTS ON W	AM ISSIO ELLS	' 7 /M g	⊜
COMPANY <u>Carper Drilling (</u>				ew Mexico	
	LL NO. <u>1</u>	UNIT N POOL	S 35 Undesign	T_16_S	R_34.E
This is a Report of: (Check appr Beginning Drilling Opera Plugging			Results of Remedial Other		sing Shut-off

Detailed account of work done, nature and quantity of materials used and results obtained.

Spotted 10 sack cement plug at total depth, 4850. Filled hole with heavy mud to 1727. Spotted 20 sack cement plug from 1632 to 1727 feet which is in and out of 7ⁿ casing set at 1677 and cemented back to the surface. Filled hole with heavy mud from 1632 to 30 feet. Filled hole with cement from 30 feet to surface and set a 4ⁿ pipe marker in the top. Leveled location.

Verbal approval for plugging procedure was obtained by A. L. Pierce on 3-26-58.

FILL IN BELC	OW FOR RE	MEDIAL WO	ORK REPORTS ONI	LY				
Original Well	Data:							
DF Elev.	TD	PBD	Prod. Int.	Com	Compl Date			
Tbng. Dia	Tbng De	pth	Oil String Dia	Oil Str	Oil String Depth			
Perf Interval	(s)							
Open Hole Inte	erval	Pro	ducing Formation	(s)				
RESULTS OF	WORKOVEF	₹:		BEFORE	AFTER			
Date of Test								
Oil Production	n, bbls, per	day						
Gas Productio	on, Mcf per	day						
Water Produc	tion, bbls.	oer day						
Gas Oil Ratio	, cu. ft. per	r bbl.						
Gas Well Pote	ntial, Mcf p	er day						
Witnessed by	p., inc. pany)							
OIL CONS	SERVATION	COMMISSIC	above is true	and complete	ormation given to the best of			
Name	A	Le. L.	my knowledge Name	· · · · ·	£			
Title	A	your 1 lil						
Date			Company Con	Company Carper Drilling Co., Inc.				