

# **OIL CONSERVATION COMMISSION** SANTA FE, NEW MEXICO

## **Miscellaneous Reports on Wells**

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	<b>X</b>
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

Hobbs, New Mexico Place

November 16, 1943 Date

OIL CONSERVATION COMMISSION,  
Gentlemen:

SANTA FE, NEW MEXICO.

Following is a report on the work done and the results obtained under the heading noted above at the

Neville G. Penrose, Inc. Company or Operator Lovington Lease Well No. 1 in the

NE 1/4 of Sec. 1, T. 15S, R. 35E, N. M. P. M.,  
Wildest Field, Lea County.

The dates of this work were as follows: November 6, 1943

Notice of intention to do the work was (was not) submitted on Form C-102 on \_\_\_\_\_, 19\_\_\_\_

and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

### DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

The bottom joint of 9-5/8 casing fell off and dropped down the hole where the top was found, by Halliburton Jeep, to be at 3968'. A Baker packer was set 15' from top of this joint and 60 sax of cement circulated behind it. Cement was then washed out from the top 15' of this joint. A cement bridge of 50 sax was set between 3110' & 3082' and an attempt made to bail the hole dry. Such was unsuccessful and a Baker packer was then set in the 9-5/8" at about 2960' and 800 sax of cement circulated behind the pipe. A temperature survey showed the cement to have returned to a depth of 2210' or approximately 800' from the bottom. Cement job appears OK.

Witnessed by Marks & C. Coleman Name Helmeriah & Payne & Neville G. Penrose Name

Subscribed and sworn before me this

18 day of November, 1943

Norma Belle

My commission expires Nov. 22, 1943  
Notary Public

Remarks:

I hereby swear or affirm that the information given above is true and correct.

Name Charles P. Miller

Position Agent

Representing Neville G. Penrose, Inc.

Address Ft. Worth, Texas.

Roy. Garbrough  
Name  
Inspector

Title