

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Genard Oil & Gas Company, Inc.		8. Farm or Lease Name State TA
3. Address of Operator Hobbs Pipe & Supply Company		9. Well No. 1
4. Location of Well UNIT LETTER <u>Q</u> , 1980 FEET FROM THE <u>South</u> LINE AND <u>350</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>18</u> RANGE <u>35</u> NMPM.		10. Field and Pool, or Wildcat Townsend-Walsh
15. Elevation (Show whether DF, RT, GR, etc.) U.K.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 35 lb. cement plug across perforations 10,413'-10,365'.
2. Spotted a 25 lb. cement plug at 6 1/2" casing stub at 8100'.
3. Spotted a 25 lb. cement plug at 8 5/8" casing shoe at 4639'.
4. Spotted a 10 lb. cement plug at surface with marker.
5. Hole was loaded with mud and fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>AUG 6 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 12 1970