




J F G ENTERPRISE

701 EAST MAIN / POST OFFICE BOX 100
ARTESIA, NEW MEXICO 88211-0100

TELEPHONE (505) 746-9811



December 6, 1990

Mr. Jerry Sexton
Oil Conservation Division
P.O. Box 1980
Hobbs, New Mexico 88240

Re: H.A. Townsend SWD #6-G, Section 9,
T16S, R35E. Oil Conservation Division
letter dated November 19, 1990.

Dear Mr. Sexton:

We rigged up on November 29, 1990 and notified OCD that day. Started searching for problem, and on December 4, 1990 we found a bad joint of tubing 21 joints above the packer; replaced joint. Tested casing from 8000' to surface with packer and plug. Casing good. Set packer at 10110'. Loaded casing with packer fluid and pressure tested to 300# for 30 minutes, per instructions of Jack Griffin of OCD.

I am sending a copy of the chart and a wellbore sketch.

Yours truly,

J.T. Jackson, Jr.
JFG Enterprise

JTJ:sg
Enclosures
cc: file