

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>OWDD</b>	7. Unit Agreement Name
2. Name of Operator <b>Great Western Drilling Company</b>	8. Farm or Lease Name <b>Low State</b>
3. Address of Operator <b>Box 1659, Midland, TX 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>*</b> FEET FROM THE _____ LINE AND _____ FEET FROM THE _____ LINE, SECTION <b>17</b> TOWNSHIP <b>16S</b> RANGE <b>35E</b> NMPM.	10. Field and Pool, or Wildcat <b>Townsend Morrow Gas</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4040' KB 4022' GR</b>	12. County <b>Lea</b>

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**\*Surface location: Unit A, 330' FNL, 330' FEL, Section 17**  
**Bottom hole location: Unit H, 1978.08 FNL, 897.86' FEL, Section 17**  
**Measured depth 12,581', true vertical depth 12,183.39'. On April 12, 1971 ran**  
**12,565' of new 13.5# N-80 4 1/2" casing, set at 12,581' MD. Cemented with 500 sacks**  
**Class C cement plus 2% gel plus 8#/sx salt plus 3/4 of 1% CFR2. Plugdown 5:45 a.m.,**  
**4-13-72.**

Copies of all directional surveys run to date have been sent to the Santa Fe Office of the Commission by the surveying companies.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. I. Comstock TITLE Chief Engineer DATE 4-13-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE APR 17 1972

CONDITIONS OF APPROVAL, IF ANY:

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000