

ASHMUN & HILLIARD
Eidson "B" #3
"O", Sec. 26, T-16-S, R-35-E
Lea County, New Mexico

WELL CONDITION AS OF 2-21-77

Surface Casing - 13-3/8", 48# set @ 349' w/350 sx - circ - none pulled

Intermediate Casing - 9-5/8", 36 & 40# set @ 4867' w/4000 sx - circ - none pulled - bottom 3 jts. broke loose in hole.

Intermediate Casing - 8-5/8", 32# - set @ 5000' w/64 sx. Top of cement 3960'. pulled 3890'. Left 3890 to 5000'.

Production Casing - 5-1/2", 15.5 & 17# set @ 10,200' w/200 sx pulled 9270'. Left 9270 to 10,200'.

Plugs set on 12-1-59

1st plug - 15 sx cement 9830 - 9930' in 5-1/2" csg. over perfs 10,100 - 10,116'.

2nd plug - 35 sx cement 9170-9270' - top of 5-1/2" stub in 7-7/8" hole.

3rd plug - 35 sx cement 6140-6240' - base of San Andres in 7-7/8" hole.

Well temporarily abandoned on 12-1-59.

RECEIVED

FEB 22 1977

CL CONSERVATION COMM.
HOBBS, N. M.