

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Hartford Accident & Indemnity Company Rev T. Short
(Address)

LEASE Millard Eidson "B" WELL NO. 3 UNIT 0 S 26 T 16S R 33E
DATE WORK PERFORMED January 12, 1958 POOL Shoe Bar Devonian

This is a Report of: (Check appropriate block)

<input type="checkbox"/> Beginning Drilling Operations	<input type="checkbox"/> Results of Test of Casing Shut-off
<input type="checkbox"/> Plugging	<input type="checkbox"/> Remedial Work
	<input type="checkbox"/> Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.
Set bridge plug at 3949' above perforation, and dump 2 sacks cement on top.
Fill with laden fluid from top of cement and place 30' cement plug in top.
Set marker and clean location.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name Ben Alexander
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name Ben Alexander
Position Agent
Company Hartford Accident & Indemnity Co.