

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02801
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-698
7. Lease Name or Unit Agreement Name Buffalo ARU State Com
8. Well No. 1
9. Pool name or Wildcat Townsend Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter K : 1980 Feet From The South Line and 1945 Feet From The West Line Section 18 Township 16S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) Unavailable	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Re-entry <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
9-30-97 - TIH at 7725' at report time. TIH to 8450'. Break circulation. Circulated out dehydrated mud. TIH and tagged at 8866'. Drilled to 9088' (soft). Washed down to 9151'. TIH to 9246'. Circulated 1-1/2 hours. TIH to 10400'. Condition mud. Washed down and tagged at 10633'. Drilling at 10820' at report time.
10-1-97 - Drilling at 10820'. Fell out of plug at 10900'. Washed down to 11050'. Circulated bottoms up. TIH and conditioned mud. TIH to 12007'. Rigged up swivel. Circulated gas bubble up. Conditioned mud. Circulated bottoms up. Got another gas kick. Unit broke down. Waiting on mechanics to repair unit.
10-2-97 - Continued circulating and rotating at 12007' while repairing unit. Repaired at 6:00 PM. Laid down swivel. TIH and tagged at 12851'. Drilled 3' and fell out. Washed down to TD of 13647' at 3:00 AM 10-2-97. Circulated gas bubble up. Conditioning mud at report time.
10-3-97 - TD 13647'. Circulated and conditioned mud for 4 hours. TOOH with drillpipe and drill collars. Rigged up Schlumberger. TIH with logging tools at report time.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Rusty Klein TITLE Operations Technician DATE Oct. 13, 1997
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL JOHN C. WILLIAMS
DISTRICT SUPERVISOR
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NFC 05 1997