MALIFATT

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)

Sept. 19, 1953 Artesia, N. Mex.

(Form C-103)

Following is a report on the work done and the results obtained under the heading noted above at the

Buffalo Oil Company	State "C" (Lease)		
(Company or Operator)			
Western Service Drilling Co.	. Well No. 1 in the NE 1/4 SW 1/4 of	Sec. 18	
(Contractor)	,	•	
T. 16S R. 35E NMPM, Eldson-Penn	Pool, Lea	County.	
The Dates of this work were as follows: Aug. 29, 1953		•••••	
Notice of intention to do the work (was) (was not) submitted on Form	C-102 on(Cross out incorrect words)	, 19,	
and approval of the proposed plan (was) (was not) obtained.			

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

13 3/8" OD Armco spiral weld casing was set at 357° and cemented to surface with 450 sacks of cement. Total depth 360°.

Witnessed by O. H. Goods	i an Bu	iffalo Oil Co	mpany, Field Supt.
(Name)		(Company)	(Title)
Approved: OIL CONSERVATION O	COMMISSION	I hereby certify that to the best of my kn	the information given above is true and complete
(Mame)		Position Vice	President
Engineer District	SEP 21 1953	Representing. Bu	ffalo Oil Company
(Title)	(Date)	Address 203	Carper Building, Artesia, N.M.