

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS OFFICE 000

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Columbian Carbon Company				Address 1266 Butternut, Abilene, Texas			
Lease Graham	Well No. 1	Unit Letter M	Section 9	Township 15S	Range 36E		
Date Work Performed 3-5-59		Pool Caudill			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. 100 sxs cement plug was spotted from 4700' - 5020'
2. 30 sxs cement plug was spotted in and out of the stub of 8-5/8" at 900'
3. 25 sxs cement plug was spotted in and out of the 13-3/8" at 320'
4. 10 sxs cement plug was spotted in top of hole with a 4" marker 5' above the ground.

* Verbal approval given to go ahead and plug by Erch Engbrecht.

Witnessed by Stanley Saikin	Position Superintendent	Company Hobbs Pipe & Supply Company
---------------------------------------	-----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA					
D F Elev.	T D	P B T D	Producing Interval	Completion Date	
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth		
Perforated Interval(s)					
Open Hole Interval			Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>John W. Runyan</i>	Name Columbian Carbon Company		
Title	Position Superintendent		
Date	Company Hobbs Pipe and Supply Company		