| STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT | |
|---|---|
| CALIFICATION DIVISION DISTRIBUTION BANTA FE FILE IL CONSERVATION DIVISIO P. O. BOX 2086 SANTA FE, NEW MEXICO 37501 | Farm C-183 Revised 18-1-78 |
| U.B.G.B. LAND OFFICE OPERATOR | Se. Indicate Type of Lesse State Pee State S. State Oll 6 Ges Lesse No. |
| SUNDRY NOTICES AND REPORTS ON WELL (100 HOT USE THAPPLICATION FOR DEALS TO DALL OF TO BEEREN OF PLUS DALL TO A COMPANY AND THE SERVICES AND REPORTS ON WELL (100 PORTS ON ALL) | |
| UL SPECIENTISH FOR PERMIT (FORM E-101) FOR SUEN PROPORALS;) | 7. Unit Agreement Name |
| 2. Hume of Operator i2.M. DISPOSAL 3. Address of Operator | 6. Form or Loose Heme |
| P.O. BOX 1544, Lovington, New Mexico 88260 | 9. Well No. |
| 4. Location of Well UNIT LETTER N | 10. Field and Pool, or Wildseit DEVONIAN |
| THE LINE, DECTION TOWNSHIP BANGE 36E HAPPA. | |
| 18. Elevation (Show whether DF, RT, GR, etc.) 3909 - 5 DF | 12. County |
| Check Appropriate Box To Indicate Nature of Notice, Report or Oth | Loa er Data |
| NOTICE OF INTENTION TO: SUBSEQUENT | |
| PLUE AND ABANDON ABANDON COMMENCE DRILLING OPNS. | ALTERING CASING |
| бтива | |
| 17. Describe Proposed or Completed Operations (Clearly state all persinent dates, and give persinent dates, including estim the of starting any proposed work) SEE RULE 1903. | |
| 06 July 1993 Rigged up on well and began removing disposal string. One joint of tubing was found at 3500' with a small hole. At 5400' two joints of tubing were found with large visible holes. There were no signs of scaling or build up on the exterior of the tubing. 8700' of tubing was pulled from the well, the packer set at 4834' and the 2 7/8" rams closed. The casing was loaded with brine and pressurized to 400 pounds under the BOP. There was no loss of pressure indicating the remaining tubing was sound. Pulling unit was shut down. | |
| 07 July 1993 Tubing standing in the derrick was tested the well at 5000 psi. One joint failed to pressure tes total of 23 joints (725.99') were culled from the dispo string, four with holes and the remainder for having er or collars. 23 new joints of plastic coated 2 7/8" tubi (724.54') were run on top and the packer set at 13,568. higher than previously).240 barrels of packer fluid wer into the casing and the packer bypass closed. The casin pressurized under the BOP with no sign of leaks. The BO stripped and the well head mounted. The casing was pres 500 psi and a chart run for thirty minutes(chart enclose ho sign of leaks the well was put back on disposal. | t. A sal oded pins ng 98',(1.45' e loaded g was P was |
| 10. I hereby a mily plat the intermetion above is true and complete to the best of my taswindge and belief. | ente 7 July 93 |
| Orig. Signed by Paul Kautz | AUG 10 1993 |
| CONDITIONS OF APPROVAL, IF ANTI | PATE |