

COPIES RECEIVED		
TRIBUTION		
FE		
S.		
OFFICE		
RATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2341
7. Unit Agreement Name
8. Farm or Lease Name Lea HQ State
9. Well No. 1
10. Field and Pool, or Wildcat Dean Permo Penn
12. County Lea

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER-
Name of Operator Gulf Oil Corporation		
Address of Operator Box 670, Hobbs, New Mexico 88240		
Location of Well UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 15-S RANGE 36-E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

3788' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Plugged and abandoned

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11,653' TD.

Pulled producing equipment. \*Circulated hole with mud. Spotted 100 sack cement plug from 11,475' to 10,528', across 5-1/2" casing perforations 10,740' to 10,768'. Ran free point and cut and recovered 5-1/2" casing from 6516'. Spotted 100 sack cement plug from 6566' to 6186', across 5-1/2" casing stub at 6516' and across top of Glorieta at 6332'. Spotted 50 sack cement plug from 5000' to 4800', across 8-5/8" shoe at 4934'. Spotted 30 sack cement plug from 2200' to 2100', across top of salt at 2170'. Spotted 15 sack cement plug from 50' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned April 13, 1973.

\* Ran bull plugged seal assembly and set in packer at 11,475'.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>K. J. Breazale</u>	TITLE <u>Area Engineer</u>	DATE <u>April 13, 1973</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE <u>Oil and Gas Inspector</u>	DATE <u>FEB 5 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		