| | | | | • | . • | | | | | | |
|---|-----------------|----------------|-----------------------|--|----------|--|---------------------------------------|-----------------------|----------------------------|---|--|
| NUMBER OF COPIES (ECEIVED OISTRIBUTION OISTRIBUTION SANTA FC NEW MEXICO OIL CONSERVATION COMMISSION FORM C-103 ULAG 3. LAND OFFICE OIL CONSERVATION COMMISSION (Rev 3-55) MISCELLANEOUS REPORTS ON WELLS PROBATION OFFICE (Submit to appropriate District Office as per Commission Rule 1106) | | | | | | | | | | (Rev 3-55) | |
| Name of Company Texas Pacific Oil Company P.O. Box 1069, Hobbs, New Mexico | | | | | | | | | | | |
| Lease State | | | 1 No. U | | | Township 16- | | Range | | | |
| Date Work Performed 9/14 -11/5 -1964 Pool Townsend Wolfcamp Lea | | | | | | | | | | | |
| THIS IS A REPORT OF: (Cbeck appropriate block) | | | | | | | | | | | |
| Beginning Drilling Operations Casing Test and Cer | | | | | | ent Job Dther (Explain): | | | | | |
| Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, and results obtained. | | | | | | | | | | | |
| Squeeze w/150 sks. Incor & .8 of 1% Halad-9. No squeeze. Squeeze 2nd stage w/100 sks. Incor & .8 of 1% Halad-9. Drilled cement to 6058'. Test casing w/2000# for 30 min. Test 0.K. Cleaned out to 10,726'. Perforated 10,544'-10,577' (1 shot per ft.). Acidized w/2000 gals. MCA. Acidized perfs. 10,650-10,710; 10,600-10,640' w/2000 gals. MCA. Placed well on pump 9/20/64. On 11/3/64 Treated w/20,000 gal. CRA Acid & 905,625 STD Cu. Ft. CO₂ & 500 bbls. lease crude. Placed well on pump 11/5/64. | | | | | | | | | | | |
| Witnessed by Position A. D. Asher Asst. Di | | | | | | t. Supt. Texas Pacific Oil Company | | | | | |
| | Vaner | | FILL IN BELO | W FOR RE | MEDIAL W | ORK R | | | | | |
| | TD | ORIGIN PBTD | AL WELL D | VELL DATA Producing Interval Completion Date | | | | | | | |
| D 1 2.00 | | | .746 • | 10.730 | | | | 0-10,710 | | 8/13/57 | |
| Tubing Diameter Tubing | | | Tubing Depth | | | | ter | | Oil String Depth 10.731 | | |
| 2 th - 2 Perforated In | | l. | 10,504 | | 2 | -1/2" | · · · · · · · · · · · · · · · · · · · | <u>~</u> | | • · · · · · · · · · · · · · · · · · · · | |
| 10,600 | 10' | Deadura | roducing Formation(s) | | | | | | | | |
| Open Hole Interval | | | | | | Wolfcamp | | | | | |
| RESULTS OF WORKOVER | | | | | | | | | | | |
| Test | Date of Test | | Oil Production BPD | | | | Production BPD | GOR Cubic feet/Bbl | | Gas Well Potential MCFPD | |
| Before Workover | 7/24/64 | | 82 | 128 | | | 0 | 1560 | | | |
| After Vorkover | | | 91 | 177 | | | .5 | 1945 | | <u> </u> | |
| OIL CONSERVATION COMMISSION | | | | | | I hereby certify that the information given above is true and complete to the best of my knowledge. | | | | | |
| Approved by | | | | | | NameOriginal signed by: John H. Hendrix | | | | | |
| Title , | | | | | | Position District Engineer | | | | | |
| | | | | | | | Company Texas Pacific Oil Company | | | | |