

Hobbs, New Mexico

SEE FORM C-105 ATTACHED

MEXICO "C" LEASE WELL NO. 2 - Owned and Operated by Skelly Oil Company

LOCATED IN THE SE/4 SE/4 SECTION 25-16E-36E, LEA COUNTY, NEW MEXICO

REPORT OF DRILL STEM TEST

D.S.T. 6090-6240'

1" top, 1" bottom chokes, 3 1/2" drill pipe.
Tool open 8 hours with fair blow of air continuing as fair blow. Gas to surface
in 4 hours and continued as fair blow throughout test. No fluid to surface.
Pulled drill pipe and recovered 90' of drilling mud, 540' of OASCM, est. 50% oil
and 600' of clean oil. No show of water. N.P. in and out 3255#, F.P. 45-675#,
20-Minute buildup 865#.

collected from the

REPORT ON DRILL TEST

LOCATION OF TEST SITE - 10000 - 10000 - 10000

LOCATED IN THE 10000 - 10000 - 10000

REPORT ON DRILL TEST

10000-10000-10000

In 10000, in bottom of hole, 10000 ft. drill pipe.
Total open 10 hours with 10000 ft. of air containing 10000 ft. of air.
In 10000 and containing 10000 ft. of air containing 10000 ft. of air.
Filled drill pipe and recovered 10000 ft. of air containing 10000 ft. of air.
and 10000 ft. of air. No more of water. 10000 ft. in and 10000 ft. of air.
10000 ft. of air. 10000 ft. of air. 10000 ft. of air. 10000 ft. of air.