OIL CONSERVATION COMMISSION

HOBBS. NEW MEXICO

Dec. 4, 1957

B. L. McFarland, Drilling Contractor 3612 West Wall Midland, Tex.

Dear Mr. McFarland:

Mr. Eric Engbrecht, Oil & Gas Inspector for the Commission, has made an inspection of the location for your plugged and abandoned Holder-Ross Well No. 1 in Unit J of Section 26, T-16-S, R-36-E and has found that the marker is not cemented and there is oil on the east side of the location.

Please advise this office when these things have been taken care of so that a final inspection may be made and your Report of Final Plugging approved without further delay.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery Proration Manager

ШC

UL CONSERVITION COMMISSION

HOLDS NEW MARCO

.

das'n i de la de

 $\mathbf{G}_{\mathbf{a}}$

ł

end is in the matrix, with a second of the second of

المعالية (1995) الألية الألية التركونية المعالية (1995) المعالية (1995) 1995 - المعالية (1995) (1995) المعالية (1995) (1995) (1995) 1995 - مولاية (1995) (1995) 1995 - مولاية (1996) (1995)

1997 - 199**7** - 1997 -

Nr Granter in al. State in an an a