

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work pocified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate	nature	of	report	by	checking	below.

ý

REPORT ON BEGINNING DRILLING OPERATIONS	X	REPORT ON R	EPAIRING	WELL		
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHER ALTERING CASING		R OTHERW	ISE	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON D	EEPENINC	WELL		
REPORT ON RESULT OF PLUGGING OF WEI			·····			
· · · · · · · · · · · · · · · · · · ·	July	12, 1950 Date	X1	dland, T	exas Place	
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen:						
Following is a report on the work done and the re Ralph Lowe	DIC	kinson		1		
SW/4 of Sec. 35	T	14 S	n	37E		
				Lea		~
The dates of this work were as follows:	July .	12, 1950			•••••	County.
Notice of intention to do the work was (CERCES)						
and approval of the proposed plan was (was not DETAILED ACCOUNT () obtained. (Cross out incorrect	t words.)			
The above well spudde July 12, 1950	ed 8 A.N.					
Witnessed by J. H. Massie		Ralph Low	8	r.	Po	

-	Name	Company	Title
Subscribed and sworn befor	e me this12	is true and correct.	m that the information given above
day of	July 19.	50 Name	and and
field Mar	Van Dan	Position	Agent
	Notary Public	Representing	Ralph Lowe Company or Operator
My commission expires	6-1-51	Address Midland	i, Texas
Remarks:		Y	Loc antropuli
TROVED			ML OAS INSPECTOR
JUL 1 5			J. J.

• • .

. .