NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of I				
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RE OF CASING SHI		xx	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RE OPERATION	COMPLETION		REPORT ON (Other)	
		aber 29, 1	952	Hebbs, New Mex	ci.co
Following is a report on the work	done and the results obtain	ned under tne hea	ding no	ted above at the	
Skelly Oil Company		•••••			
Rossan Drilling Compan	y	, Well No) 	(Lease)in the	of Sec,
(Contracto	r)				
The Dates of this work were as follows:					
The Dates of this work were as folows:	Depot 24, one of				
Notice of intention to do the work	(was not) submitted on F	orm C-102 on		Cross out incorrect words)	, 19,
and approval of the proposed plan			,		
and approved to the party of the	-, ,				
TO TOWN A	TITED ACCOUNT OF WOL	RE DONE AND	RESUL	TS OBTAINED	
(1	ILED ACCOUNT OF WOL	IMBER OF SAC	ks of	CEMENT ONLY)	
Total Depth 12,600'. s acks and through 2-s plug 1:45 A.M. 9/27/52	Set 5-1/2" OD cast stage tool at 9030° 2. Shut-off tester	ing at 12,59 with 900 s	KS OF 19 ¹ , c	CEMENT ONLY)	with 8 50 rilled
Total Depth 12,600°. s acks and through 2-s plug 1:45 A.M. 9/27/52	Set 5-1/2" OD cast stage tool at 9030° 2. Shut-off tester	ing at 12,59 with 900 s	KS OF 19 ¹ , c	emented around sheet WOC 72 hours and di	with 8 50 rilled
Total Depth 12,600'. s acks and through 2-s plug 1:45 A.M. 9/27/52	Set 5-1/2" OD caststage tool at 9030's. Shut-off tested	ing at 12,59 with 900 at 0K. ly 0il Company) I hereby ce to the best	RS OF	CRAFFT OHLY) emented around sheet work and distribute the information given above is to the information given g	
Total Depth 12,600°. s acks and through 2-s plug 1:45 A.M. 9/27/52 Witnessed by E. R. Dedts (Name)	Set 5-1/2" OD caststage tool at 9030's. Shut-off tested	ing at 12,59 with 900 at 0K. ly Oil Company) I hereby ce	RS OF	CRAFFT OHLY) emented around sheet work and distribute the information given above is to the information given g	
Total Depth 12,600°. s acks and through 2-s plug 1:45 A.M. 9/27/52 Witnessed by E. R. Dedts (Name)	Set 5-1/2" OD caststage tool at 9030's. Shut-off tested	ing at 12,59 with 900 at 0K. 1y 0il Company) I hereby ce to the best Name	rtify that of my k	CRAFFT OHLY) emented around sheet work and distribute the information given above is to the information given g	true and complete

				• .	
					5
					•
					1
					17
					in the state of the state of
			•		And in the contract of the con
					The state of the s
					The state of the s
		٠		1	
					· illumination