

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

LL API NO. 30-025-05300
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Denton
8. Well No. 13
9. Pool name or Wildcat Denton (Devonian)
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3803' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Fasken Oil and Ranch, Ltd.

3. Address of Operator
303 W. Wall Ave., Suite 1800, Midland, TX 79701-5116

4. Well Location
Unit Letter D : 660 feet from the North line and 762 feet from the West line
Section 11 Township 15S Range 37E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

A mechanical integrity test performed 1-23-01 failed. Repair operations are due 4-28-01 per notice 2-1-01.

Fasken respectfully requests a 60 day extension on the date to commence repair operations due to workover rig availability. Fasken is currently securing partner approvals to attempt to repair the well and return to producing status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carl Brown TITLE Petroleum Engineer DATE 4-20-01

Type or print name Carl Brown
(This space for State use)

Telephone No. (915) 687-1777

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

5
C

