## W MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS OFFICE OCC

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 bays after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shuf-oil, result or plugging of well, iı

picted. It should be signed and file result of well repair, and other in instructions in the Rules and Regi	nportant ope	rations, even though the		-		• .
	:	Indicate Nature of Repo	rt by Checking Belo	)W		
		REPORT ON RESUI OF CASING SHUT-		REPORT ON REPAIRING WELL		
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECORD OPERATION	MPLETION	REPORT ON (Other)		
		April (Date)	19, 1954	Midla	ind, Texas	
Following is a report on the	work done	and the results obtained	under the heading no	oted above at the		
The Texas Company (Company or Operator)			Mamie Graham			
Cactus Drilling	Compan	У	Well No. 4		SW My of Sec	30
16-S , R 37-E , NMPM	tractor)					
The Dates of this work were as fold		See Below				
he Dates of this work were as fold	)ws:	,			·	
Notice of intention to do the work	(was	not) submitted on Form	C-102 on	Cross out incorrect wor	is)	., 19,
nd approval of the proposed plan						
D	ETAILED A	ACCOUNT OF WORK I	ONE AND RESUL	TS OBTAINED		
	<b>T</b> D	: 350 - Redbec	ie			
Spudded at 2	:00 A.M	. April 11, 19	954.			
Ran and cemen	nted ll t circu	joints 333' (lated. Comple	of 13 3/8" of ted at 8:20	easing at 34 P.M. April	7' with 11, 1954	•
Commenced dracasing by pressure		cement at 11:0		12, 1954	. Temted	
casing by bresser	a me cho	d. leafed of	ay •			
Witnessed by						
(N	ame)		(Company)		(Title)	
Approved:	ON COMM	IISSION	I hereby certify that to the best of my be	the information give	n above is true and	complete
D-4 ()to	mley	***************************************	Name	cofa		
	Vame)		Position Asst			<del></del>
n de la companya della companya de la companya della companya dell	Ø.		recht cromming	Texas Com		
(Title)		(Date)	Address Box	1270 Mid	land, Texa	3