


N. M. O. C. C. COPY
(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 029405 B
Unit Lease

RECEIVED
FEB 22 1961
N. M. O. C. C. OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT (Temporary) <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wm. Mitchell B _____ January 31 _____, 1961

Well No. 40 is located 1980 ft. from (N) line and 660 ft. from (E) line of sec. 18

NE/4 SE/4 Sec. 18 17-S 32-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Maljamar Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Subject well was temporarily abandoned 12-30-60. The well contains 241' of 8 5/8" OD 24# J-55 casing set at 249', and 4216' of 5 1/2" OD 14# J-55 casing set at 4196'. Production casing is perforated from 3930-34'. The well is not plugged, however, complete wellhead equipment is installed. The location has been cleaned up and will be kept in a neat and orderly condition during the period of temporary abandonment. The well was temporarily abandoned, instead of permanently abandoned, in order to allow time for further study and evaluation before final disposition is made.

USGS-3 WAM File

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Rowley Building

Artesia, New Mexico

By [Signature]

Title District Superintendent