

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLahd Office **Las Cruces**Lease No. **029405-A**

Unit

AUG - 8 1950

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico, Aug. 7, 1950

Mr. Mitchell A

Well No. **19-F** is located **1980** ft. from **N** line and **2180** ft. from **E** line of sec. **19****SW 1/4 Sec. 19****17****32E****NMPM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Maljamar-Paddock (Proposed)**Lea****New Mexico**

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On August 6, 1950, at 9:00 A.M., 8 5/8" casing was cemented at total depth, 2490' with 200 sacks in first stage and 100 sacks in second stage through cementing collar at 782'. After waiting 48 hours the plug will be drilled and pipe tested for 30 minutes with 600 psi. If a satisfactory job is indicated, drilling will then be resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **BUFFALO OIL COMPANY**Address **203 Carper Bldg.****Artesia, N. Mex.**

By

Vice-President

Title