

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

X				

UNITED STATES GEOLOGICAL SURVEY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
MAY 30 PM 3:03

Lease No. 02405 A
Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Mr. Mitchell A. May 29, 1962

Well No. 23 is located 660 ft. from N line and 460 ft. from E line of sec. 20
N4/4 NW/4 Sec. 20 17-3 32-5 R17W
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Malpais-Padlock Lea New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3977 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)
 Ran 5391' 4 1/2" OD casing, set at 5370' with 490 sacks cement and 45 gallons Latex (The Halliburton Company). Top of cement by temperature survey at 1815'. Plug down at 8:30 P.M. 5-27-61. WC 24 hours. Tested casing with 1,000# for 30 minutes. No pressure drop.

UNCL-3 N100-2 N41 File

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company
 Address Rowley Building
Artesia, New Mexico
 By _____
 Title District Superintendent

CONFIDENTIAL

[illegible]