

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersede: Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Cities Service Oil Company</b>	8. Farm or Lease Name <b>Westall A</b>
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Co., Box 2010, Hobbs, N.M. 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>D</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>36</b> , TOWNSHIP <b>17</b> RANGE <b>32</b> NMPM.	10. Field and Pool, or Wildcat <b>Maljamar-Grayburg-San Andre</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>U.K.</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx cement plug @ 4600'.
2. Spotted a 25 sx cement plug at 6" casing stub @ 1900'.
3. Spotted a 25 sx cement plug at 8-5/8" casing shoe @ 1300'.
4. Spotted a 10 sx cement plug at surface with marker.
5. Hole was loaded with mud laden fluids.
6. Well was plugged and abandoned on 1/7/71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Harold Schmeider</i>	TITLE <b>Agent</b>	DATE <b>1/19/71</b>
APPROVED BY <i>John W. Runyan</i>	TITLE	DATE <b>JUL 2 1975</b>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 21 1971

OIL CONSERVATION COMM.  
HONOLULU, H. I.