

Form 9-331a
(March 1942)

1943

Frank B. Hale

INDERS OFFICE 000

Budget Bureau No. 42-R308.1
Approved March 11-20-40.

(SUBMIT IN TRIPLICATE)


1963 JUN 24 AM

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Up to



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Given "R"

April 11

1943

Well No. 10-13 is located 2580 ft. from N line and 2595 ft. from W line of sec. 36

10-13 (4 Sec. and Sec. No.) 10-13 (Twp.) 36 (Range) W (Meridian)
10-13 (Field) 10-13 (County or Subdivision) 10-13 (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 4-10 we drilled to a total depth of 3992'. 4-11 the well was cleaned out from 3992' to 3921'. A 3 1/2" shell using 90 parts of nitro was run from 3992' to 3921' - total of 441. 100' of gravel was used for a temp. casing. The well was then cleaned out to 3921'. On 4-12 a 2" shell, using 90 parts of nitro, was run from 3921' to 3901' - total of 20'. A 100' gravel trap was used on this job. Well was then cleaned out to a total depth of 3902' on 4-12. Well was pulled and washed for 24 hours. On 4-13, 5936' of 2" upset tubing was run with perforations set at 3956'.

(Above work confirmed in telephone conversation between Frank B. Hale and M. Bailey - 4-11-43)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Carrer Drilling Company, Inc.

Address Carrer Building

Mexico, D.F., Mexico

By Frank B. Hale