

Form 9-231a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 029509-A  
Unit H

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, N. Mex. Dec. 4, 1951

Blair A  
Well No. IF #19 is located 2530 ft. from N line and 215 ft. from E line of sec. 21  
SE 1/4 Sec. 21 17S 32E NM 10N  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Palmar Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4021 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On November 29, 1951, 10-3/4" OD 40.5# second hand casing was cemented at 74' with 60 sacks. The cement circulated to surface. After 24 hours waiting time, drilling operations were resumed. No water was encountered and this string serves only as a conductor.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BUFFALO OIL COMPANY

Address 203 CAMPER BUILDING  
ARTESIA, NEW MEXICO

By Al Lewis  
Title Vice President