




LOCATE WELL CORRECTLY

FORMATION RECORD - Continued
UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

U. S. LAND OFFICE Las CrucesSERIAL NUMBER 029410-HLEASE OR PERMIT TO PROSPECT 1000

1963 JUN 21 AM 7:48

LOG OF OIL OR GAS WELL

Company Carper Drilling Co., Inc. Address Artesia
 Lessor or Tract Simon Field Malinar State New Mexico
 Well No. I. P. 28 Sec. 30 T. 173 R. 32 Meridian N.M.P.M. County Lea
 Location 241 1/2 {N.} of 3 Line and 140 {E.} of 3 Line of Sec. 30 Elevation 3913
 (Derriack floor relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Signed _____

Date September 5, 1950Title Vice-President

The summary on this page is for the condition of the well at above date.

Commenced drilling April 4, 1950 Finished drilling June 20, 1950

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

No. 1, from 2290 SS 0 & G No. 4, from 3704 to 3709 SS G
 No. 2, from 3063 to 3075 SS 2 & G No. 5, from 3715 to Increase in G.
 No. 3, from 3534 to 3548 SS G No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from 600 to 670 (G) No. 2, from 670 to 680 (G)
 No. 2, from 680 to 690 (G) No. 3, from 690 to 700 (G)

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From--	To--	
10-3/4	40	8	3000	3000					
8-5/8	30	8	3000	3000					
7	20	8	3000	3000					

HISTORY OF OIL OR GAS WELL

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
10-3/4	31	25	By hand		
8-5/8	973	50	Malibarton		
7	3676	300			

Circulated to surface

PLUGS AND ADAPTERS

Heaving plug Material _____ Length _____ Depth set _____