

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Shelby Oil Co.				Address 1219 Davis Ave. Alamogordo, N.M.			
Lease Shelby Oil Co.	Well No. 1	Unit Letter B	Section 20	Township 1N	Range 2E		
Date Work Performed 4-2-56	Pool Shelby (100%)			County Doña Ana			

THIS IS A REPORT OF: (Check appropriate block)

- ☒ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Set 25 sq. ft. of cement at 3440'. Flood 25 sq. cement at base of well at 3440'. Flood 25 sq. cement at surface at 1330' et. Flood 25 sq. cement at base of surface at 1330'. Flood 25 sq. cement at surface. Last flood at 1330' marker at well.

Witnessed by J. J. Proctor	Position Gen. Mgr.	Company Shelby Oil Co.
-----------------------------------	---------------------------	-------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA					
D F Elev.	T D	P B T D	Producing Interval	Completion Date	
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth		
Perforated Interval(s)					
Open Hole Interval			Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by Leslie G. Clements		Name J. J. Proctor	
Title		Position Gen. Mgr.	
Date		Company Shelby Oil Co.	