

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Ashmun & Hilliard				Address 303 N. Marlenfeld St., Midland, Texas			
Lease Eidson	Well No. 1	Unit Letter J	Section 26	Township 16-S	Range 35-E		
Date Work Performed 9-10-65	Pool Shoe Bar Penn			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Operator drilled well to a depth of 4842 feet, ran 8-5/8 inch and set at 4840 feet as follows: 278.59', 36#, J-55; 1542.49', 32#, J-55; 1214.69', 32#, H-40 and 1809.65', 24#, J-55. Cemented casing with 600 sacks 50-50 poxalix plus 100 sacks neat cement. Waited on cement 24 hours. Pressured up for 30 minutes to 1000#. Held okay.

Witnessed by J. B. Ashmun	Position Partner	Company Ashmun & Hilliard
-------------------------------------	----------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	

Perforated Interval(s)

Open Hole Interval

Producing Formation(s)

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name
Title	Position
Date	Company

Partner
Ashmun & Hilliard