

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Ashmun & Hilliard				Address 303 N. Marlenfeld St., Midland, Texas			
Lease Eidson		Well No. 1	Unit Letter J	Section 26	Township 16-S	Range 35-E	
Date Work Performed 8-1 and 8-9-65		Pool Shoe Bar Penn			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☒ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Operator spudded well 2:00 P.M. August 1, 1965. Drilled to total depth of 391 feet, ran 11-3/4 inch, 40# new casing to 382 feet, cemented with 400 sacks regular neat plus 2% calcium chloride. Cement circulated. Waited on cement 24 hours, pressured tp to 500#. Held okay for 30 minutes.

Witnessed by Jim E. West	Position Prod. Supt.	Company Ashmun & Hilliard
------------------------------------	--------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

Approved by	I hereby certify that the information given above is true and complete to the best of my knowledge.
Title	Name Jim E. West
Date	Position Production Superintendent
	Company Ashmun & Hilliard