| DISTRIBUTION | | |
|---|---|---------------------------------|
| SANTAFF | | Form C-103 Supersedes Old |
| SANTA FE | NEW MEXICO OIL CONSERVATION COMMISSION $(0,0)$ | C-102 and C-103 |
| FILE | | Effective 1-1-65 |
| U.S.G.S. | 100 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 | 5a. Indicate Type of Lease |
| LAND OFFICE | | |
| OPERATOR | | State State Oil & Gas Lease No. |
| SUNDRY NOTIC | CES AND REPORTS ON WELLS | All Illian on a das Fease Wo. |
| USE "APPLICATION FOR PER 1. | CES AND REPORTS ON WELLS DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. MIT -" (FORM C-101) FOR SUCH PROPOSALS.) | |
| OIL GAS WELL OTHER- | | 7. Unit Agreement Name |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Greathouse, Pierce & Davis | | Caudill |
| 3. Address of Operator | | 9. Well No. |
| 609 Midland Mational Bank B | ildg. | #1 |
| 4. Location of Well | | 10 12:11 15 1 |
| UNIT LETTER | FEET FROM THE NOTTH LINE AND 1980 FEET FROM | Wildcat |
| THE LINE, SECTION 9 | TOWNSHIP 15-8 RANGE 36-8 NMPM | |
| | | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 3912.5 gr | Les |
| Check Appropria | nte Box To Indicate Nature of Notice, Report or Ot | her Data T REPORT OF: |
| PF050011 051100111 | | REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON PULL OR ALTER CASING | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| POLL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOB | |
| ОТНЕР | OTHER | |
| orner | | |
| 20 sack coment 20 sack coment | location cleaned, levelled and marker set gan 8-6-66: 2 plug @ 47001 - 4600' 2 plug @ 2183' - 2083' 3 plug @ top & coment marker. | . Plugging |
| | | |
| 3. I hereby certify that the information above is true | e and complete to the best of my knowledge and belief. | 0-9-64 |
| GNED S. I hereby certify that the information above is true | _ | 9-8-66 |
| GNED S. Kur | TITLE PARTNER | 9-8-66 |