

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Stoltz & Company	5. State Oil & Gas Lease No. K-3925
3. Address of Operator c/o Oil Reports & Gas Services, Box 763, Hobbs, New Mexico	7. Unit Agreement Name
4. Location of Well UNIT LETTER C , 330 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 15 S RANGE 32 E NMPM.	8. Farm or Lease Name Standard State
	9. Well No. 1
	10. Field and Pool, or Wildcat N. Anderson Ranch
15. Elevation (Show whether DF, RT, GR, etc.) 4297.5 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 2/8/68 as follows:

25 sacks across perfs 10,170-260
Cut & pulled 4 1/2" casing from 8740
25 sacks across 4 1/2" casing stub
25 sacks at 5780
25 sacks across 8 5/8" casing shoe at 4000
Cut & pulled 8 5/8" casing from 1260
25 sacks across 8 5/8" casing stub
25 sacks across 13 3/8" casing shoe at 480
10 sacks at surface with regulation marker
Mud between all plugs

Location is cleared and levelled and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Th. L. Smit TITLE Agent DATE 4/26/68
APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: