

YATES PETROLEUM CORPORATION  
Union AQZ State #1  
Section 14-T16S-R34E  
Lea County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 13020-13084' (Morrow): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 30".  
RECOVERY: 2696' of water cushion, 68' of water and 31' of rathole mud. SAMPLER:  
.007 cfg and 25 cc water. PRESSURES: IHP 6682; IFP 1242-1305; ISIP 3995; 2nd FP  
1318-1322; 2nd SIP 4901; FFP 1337-1334; FHP 6691

DST #2 13204-13235' (Morrow): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 30".  
RECOVERY: 2770' of water cushion and 60' of rathole mud. SAMPLER: .057 cfg and  
2500 cc mud. PRESSURES: IHP 6943; IFP 1281-1283; ISIP 2907; 2nd FP 1278-1278;  
2nd SIP 3969; FFP 1277-1273; FHP 6911