

COPIES RECEIVED	
TRIBUTION	
FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Gulf Oil Corporation	5. State Oil & Gas Lease No. K-4676
3. Address of Operator Box 670, Hobbs, New Mexico 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 16-S RANGE 34-E NMPM.	8. Farm or Lease Name Lea PS State
	9. Well No. 1
	10. Field and Pool, or Wildcat No. Vac Lower No.
15. Elevation (Show whether DF, RT, GR, etc.) 4078' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10,875' TD.

Pulled producing equipment. Ran CI BP and set at 10,006'. Dumped 2 sacks of cement on top of BP. Set CI BP at 8475'. Loaded hole with heavy mud. Dumped 4 sacks of cement on top of BP. Cut and recovered 5-1/2" casing from 5275'. Spotted 21 sack cement plug from 5325' to 5225', across 5-1/2" stub at 5275'; 29 sack cement plug from 4650' to 4550', across San Andres; 30 sack cement plug from 4140' to 4040', across 8-5/8" shoe at 4090'. Cut and recovered 8-5/8" casing from 1171'. Spotted 50 sack cement plug from 1221' to 1121', across 8-5/8" stub at 1171'; 72 sack cement plug from 428' to 328', across 13-3/8" shoe at 378' and 10 sack cement plug from 13' to surface. Installed dry hole marker. Plugged and abandoned April 2, 1974. Will advise when location is ready for your inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

B. J. Parbratz

TITLE

Area Engineer

DATE

April 2, 1974

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: