

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9538	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Forest Oil Corporation	8. Farm or Lease Name State "A"
3. Address of Operator P. O. Box 4106 - Odessa, Texas 79760	9. Well No. 3
4. Location of Well UNIT LETTER K 1,650 FEET FROM THE South LINE AND 2,310 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 16-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4182' DF, 4183' RT, 4170' GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-10-68

Through open end drill pipe Halliburton Oil Well Cementing Company placed 25 ex. cement plugs at the following intervals:
11-485' - 11,575' T.D.; 9,703' - 9,790' Wolfcamp; 7,934' - 8,021' Abo;
5,880' - 5,967', Glorieta; 4,451' - 4,538', across 8-5/8" casing shoe,
0' - 12', top 8-5/8" casing.
No casing was removed from well.

A steel plate was welded on top of 13-3/8" casing and a regulation 4" steel marker with identification data was welded to the side of the 13-3/8" casing.

When location has been cleared, pits and cellar leveled and junk removed, the Commission will be notified to make inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. R. Wright* TITLE Division Production Sup't. DATE 1-11-68
APPROVED BY *John W. Runyon* TITLE Geologist DATE _____
CONDITIONS OF APPROVAL, IF ANY: