NO. OF COPIES R	ECEIVED			Form C-103
DISTRIBUT	ION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION		Effective 1-1-65	
FILE			**	5a. Indicate Type of Lease
U.S.G.S.				State X Fee
OPERATOR				5, State Oil & Gas Lease No. K. 4619
	STIFTON	V NOTICES AND DEPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 1.				7. Unit Agreement Name
OIL X	GAS WELL	OTHER-		7. Omt Agreement Nume
2. Name of Operator				8. Farm or Lease Name
Pennzoil United, Inc. 3. Address of Operator				State "33"
o, nadross or open		Drawer 1828 - Midland, 1	Texas 79701	1
4. Location of Wel	II The state of th			10. Field and Pool, or Wildcat
UNIT LETT :R _	<u> </u>	560 FEET FROM THE South	LINE AND 1980 FEET FR	"" Undesignated
тнеЕа	IST LINE, SECTIO	n 33 TOWNSHIP	S RANGE 34-E NM	PM.
mmm		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
4079.8 GL				Lea
16.	Check A	Appropriate Box To Indicate N	ature of Notice, Report or	Other Data
	NOTICE OF IN			ENT REPORT OF:
PERFORM REMEDIA		PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABAN		FEOG AND ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CA		CHANGE PLANS	CASING TEST AND CEMENT JOB X	TOO AND ADARDON WENT
	_		OTHER	
OTHER				
17. Describe Frop		erations (Clearly state all pertinent deta	ils, and give pertinent dates, includ	ling estimated date of starting any proposed
•				
10-29-68	Spudded 17 1/2" hole at 2:00 P.M Drilled to 365' - Ran 13 3/8" OD, 48# csg. to 364' - Cement w/200 sx Class "H" 6% gel plus 150 sx Class "H" 2% HA-5. Plug down at 11:30 P.M Cement circulated O.K.			
10-30-68	After 18 hrs WOC, tested csg. to 900# for 30 min - 0.K.			
33 4 40		- 100		
11-4-68	Drilled 11" hole to 4,000' - Ran 8 5/8" OD, 24# & 32# casing to 4,000' Cement w/450 sx Class "" 50/50 posmix 6% gel w/23 1/2# salt per sack plus 150 sx Class "H" w/8# salt per sack Plug down at 8:45 P.M.			
11-5-68	Ran temperature survey - Top cement 2800' - After 26 hrs, tested csg. w/1500# for 30 min - 0.K.			
18. I hereby certify	y that the information	above is true and complete to the best o	of my knowledge and belief.	
		/ ° /		
SIGNED	Saadu	INC	Drilling Superintender	nt date 11-7-68
SIGNED)	Laadu 7	O TITLE	Drilling Superintende	nt DATE 11-7-68
SIGNED APPROVED BY	Janely	Rungen TITLE	Drilling Superintende	nt DATE 11-7-68