

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3412	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company		8. Farm or Lease Name Great Western - State
3. Address of Operator P. O. Box 1659 Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER F , 2310 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 15-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Anderson Ranch, North
15. Elevation (Show whether DF, RT, GR, etc.) 4289 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

A cast iron bridge plug was set at 9950' and 10 sacks of cement were placed on top of the plug. The hole was filled with 9.0#/gal. mud; 8900' of 4-1/2" casing and 2335' of 8-5/8" casing were recovered. 25 sack cement plugs were spotted as follows: 8900; 7600; 6900; 5700; 4180; 2335; 445' and at the surface. Plugging operations completed 1-20-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>R. J. Comstock</i></u>	TITLE Chief Engineer	DATE February 16, 1970
APPROVED BY <u><i>John W. Runyon</i></u>	TITLE <u><i>C. J. [illegible]</i></u>	DATE <u><i>Feb 17, 1970</i></u>
CONDITIONS OF APPROVAL, IF ANY:		