Form 3160-5 June 1990)	JITED S		
		STATES	FORM APPROVED
			Budget Bureau No. 1004-0135
	BUREAU OF LAND		Expires: March 31, 1993
			5. Lease Designation and Serial No.
			LC 0572100
	SUNDRY NOTICES AND F	REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for propo	sals to drill or to deepen or n	eentry to a different reservoir.	
	I FOR PERMIT " for such pr	•	
			7. It Unit of CA, Agreement Designation
	SUBMIT IN TRIP	LICATE	
Type of Well	······		
	INJECTION		
Well Well Oth Name of Operator	her		MCA Unit
			Well #315
CONOCO, INC.			
			30 025 24128
	land, Texas 79705-4500,915 686-	5424 915 684-6381	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R.	., M., or Survey Description)		Maljamar Grayburg San Andres
Surface: 1345' FSL & 1295' FWL TD: Sec 27, TI7S, R32E, Unit Ltr. L			11. County or Parish, State
			Lea, NM
	TE DOVIN TO MOTO	NATURE OF NOTIOE DEPOS	
CHECK APPROPRIA	TE BOX(S) TO INDICATE	NATURE OF NOTICE, REPOR	I, OR OTHER DATA
TYPE OF SUBMISS	SION	TYPE OF ACT	TION
Notice of Intent		Abandonment	Change of Plans
		Recompletion	New Construction
X Subsequent Report	t	Plugging Back	Non-Routine Fracturing
_		Casing Repair	Water Shut-Off
Final Abandonment	t Notice	Altering Casing	Conversion to Injection
		X attempt to run liner	Dispose Water
			Note: Report results of multiple completion on Well
			Completion or Recompletion Report and Log form.)
directionally drilled, give subsurfa			
7-20-98: Move in and 4 I/2" string m POOH - attern 7-2I-98: Picked up and @ I939', unab 7-22-98: Ran in hole v collars, remov	hill, 2-3 I/8" drill collars on 2 npt to find bad spot. SION. d RIH w/ 2 3/8" mule shoe, ole to work wash pipe into c with 2-3 I/8" drill collars & 2	2 7/8" tubing, picked up & ran in 2 3/8" tubing, stacked out 1939', o string mill, drill collars on 2 3/8" casing, POOH. SION. 2 3/8" tubing, POOH & laid down ad, rigged down & moved off.	n hole w/I0' 2 3/8" PUP jt., dropped down to 1954', " tubing; parted casing
7-20-98: Move in and 4 I/2" string m POOH - atter 7-2I-98: Picked up and @ I939', unab 7-22-98: Ran in hole v collars, remov	nill, 2-3 1/8" drill collars on 2 hpt to find bad spot. SION. d RIH w/ 2 3/8" mule shoe, ble to work wash pipe into c with 2-3 1/8" drill collars & 2 yed BOP & installed wellhe of 2 7/8" J-55 tubing in hol Title REC	2 7/8" tubing, picked up & ran in 2 3/8" tubing, stacked out 1939', o string mill, drill collars on 2 3/8" casing, POOH. SION. 2 3/8" tubing, POOH & laid down ad, rigged down & moved off.	n hole w/I0' 2 3/8" PUP jt., dropped down to 1954', " tubing; parted casing
7-20-98: Move in and 4 I/2" string m POOH - attern 7-2I-98: Picked up and @ I939', unab 7-22-98: Ran in hole v collars, remov Left one joint of Left one joint of Signed Construction of approval, if any:	Ann I Title	2 7/8" tubing, picked up & ran in 2 3/8" tubing, stacked out 1939', o string mill, drill collars on 2 3/8" casing, POOH. SION. 2 3/8" tubing, POOH & laid down ad, rigged down & moved off. e, will evaluate.	n hole w/I0' 2 3/8" PUP jt., dropped down to I954', " tubing; parted casing n 2 3/8" tubing & drill Dete <u>8-I3-98</u>
7-20-98: Move in and 4 1/2" string m POOH - attern 7-21-98: Picked up and @ 1939', unab 7-22-98: Ran in hole v collars, remov Left one joint of Left one joint of Signed Conditions of approval, if any.	nill, 2-3 I/8" drill collars on 2 npt to find bad spot. SION. d RIH w/ 2 3/8" mule shoe, le to work wash pipe into c with 2-3 I/8" drill collars & 2 ved BOP & installed wellhe of 2 7/8" J-55 tubing in hol Title	2 7/8" tubing, picked up & ran in 2 3/8" tubing, stacked out 1939', o string mill, drill collars on 2 3/8" casing, POOH. SION. 2 3/8" tubing, POOH & laid down ad, rigged down & moved off. e, will evaluate.	n hole w/I0' 2 3/8" PUP jt., dropped down to I954', " tubing; parted casing n 2 3/8" tubing & drill Dete <u>8-I3-98</u>