| | | A. |
|---------------------------------|--|--------------------------------|
| NO. OF COPIES RECEIVED | | - |
| DISTRIBUTION | | Form C-103 Supersedes Old |
| SANTA FE | NEW MEXICO OIL CONSERVATION COMMISSION | C-102 and C-103 |
| FILE | | Effective 1-1-65 |
| U.S.G.S. | | |
| LAND OFFICE | | 5a. Indicate Type of Lease |
| OPERATOR | | State Fee X |
| | | 5. State Oil & Gas Lease No. |
| | DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. | |
| I. OIL GAS WELL WELL | OTHER- | 7. Unit Agreement Name |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Perry R. Bass | | |
| 3. Address of Operator | | W. T. Reed 9. Well No. |
| Box 1178, Monahans, Texas 79756 | | |
| Location of Well | | 10. Field and Pool, or Wildcat |
| UNIT LETTER | 660 FEET FROM THE West LINE AND 1980 FEET FROM | WAD deat |
| THE South LINE, SEC | TION 24 TOWNSHIP 155 RANGE 35E NMPM. | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 3950' GL | Lea |
| l6. Check | | |
| NOTICE OF | Appropriate Box To Indicate Nature of Notice, Report or Oth INTENTION TO: SUBSEQUENT | er Data REPORT OF: |
| | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON | CHANGE PLANS CASING TEST AND CEMENT JOB | PLUG AND ABANDONMENT |
| OTHER | OTHER | |
| | | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7 7/8" hole to 10,467'. DST #1 from 10,414' to 10,462'. No gas or fluid to surface. Tool open two hours. Good blow air while SC blanked off. Very weak blow when opened to pit. REC: intermittent gas 185'-10,039', 20' OCM, 87' heavy O&GCM, 83' heavy O&GCM (foam). Sample chamber contained 0.2 CF gas, 700 cc 40.0° oil and 800 cc O&GCM. Pressure on sampler 25 psi. BHT 150°. Drilled ahead with 7 7/8" bit to 10,755'. DST #2 from 10,755' back to 10,648'. No gas to surface. Tool open two hours on 5/8" BHC, no water blanket. Fair blow air throughout test. REC: 1980' free gas, 40' slightly GCM. Sample chamber contained 0.06 CF gas and 800 cc slightly 0%CCM. EHT 1546. Continued drilling 7 7/8" hole to 11,250' TD. Reached TD @ 9:00 AM 1-19-73. Ran gamma ray-acoustic logs. Tagged bottom @ 11,254'. Rigged up to plug. Spotted 40 sks Cl. H cement @ 11,250' - est. top of plug @ 11,120'. Spotted 40 sks Cl H cement @ 10,400' - est. top of plug @ 10,270'. Spotted 40 sks Cl H cement @ 9,820' est. top of plug @ 9,690'. Spotted 40 sks Cl H cement @ 8,140' - est. top of plug @ 8,010'. Spotted 40 sks Cl H cement @ 6,220' - est. top of plug @ 6,090'. Spotted 40 sks Cl H cement @ 4,740' (50' below 8 5/8" csg) - est top of plug @ 4,610'. Perforated 8 5/8" csg with six (6) shots over 15" interval. Bottom perforation @ 430'. Established circulation - pumped 210 sks Cl H, 15.6#/gal cement. Followed plug with 22 bbls mud and wire line. Stopped plug @ 380'. Circulated out 4 bbls cement. Job completed @ 2:15 AM, 1-21-73. Spotted 10 sks Cl H cement from 30' to surface. Intervals between plugs filled with 8.8#/gal mud. Installed permanent well marker. Cleaned location, fenced reserve pit. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY JANGU. MUNYAM TITLE

CONDITIONS OF APPROVAL, IF ANY: