

**NEW MEXICO OIL CONSERVATION COMMISSION  
FIELD TRIP REPORT**

I N S P E C T I O N	C L A S S I F I C A T I O N	F A C I L I T Y	H O U R S	Q U A R T E R  H O U R S

Name GARY W. WINK Date \_\_\_\_\_ Miles \_\_\_\_\_ District I  
 Time of Departure 7 AM Time of Return 4 PM Car No G-04719

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature \_\_\_\_\_

ZIA ENERGY - GRIZZELL B#1 - G 8-22-37

CELLAR FULL B#3 - H 8-22-37

Mileage

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other \_\_\_\_\_

Per Diem

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other \_\_\_\_\_

Hours

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other \_\_\_\_\_

**TYPE INSPECTION  
PERFORMED**

H = Housekeeping  
 P = Plugging  
 C = Plugging Cleanup  
 T = Well Test  
 R = Repair/Workover  
 F = Waterflow  
 M = Mishap or Spill  
 W = Water Contamination  
 O = Other

**INSPECTION  
CLASSIFICATION**

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SND, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
 R = Inspections relating to Reclamation Fund Activity  
 O = Other - Inspections not related to injection or The Reclamation Fund  
 E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

**NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED**

D = Drilling  
 P = Production  
 I = Injection  
 C = Combined prod. inj. operations  
 S = SND  
 U = Underground Storage  
 G = General Operation  
 F = Facility or location  
 M = Meeting  
 O = Other

ANNA STEWART  
BARRY  
HOBBS

8:40 N  
ANNA STEWART  
LOT 4 - 30-21-36  
COWINGS

MERIT - GILMORE W) #1  
7405 & W  
LOT 4 AS U.L.M. FED.

30-21-36



ANNA STEWART